

ORIGINAL



0000017770

LAW OFFICES

**FENNEMORE CRAIG**

A PROFESSIONAL CORPORATION

50

**PATRICK J. BLACK**

Direct Phone: (602) 916-5400

Direct Fax: (602) 916-5600

pblack@fclaw.com

OFFICES IN:

PHOENIX, TUCSON,

NOGALES, AZ; LINCOLN, NE

3003 NORTH CENTRAL AVENUE

SUITE 2600

PHOENIX, ARIZONA 85012-2913

PHONE: (602) 916-5000

FAX: (602) 916-5999

April 28, 2005

Mr. Brian Bozzo, Compliance Manager  
Utilities Division

Arizona Corporation Commission


1200 W. Washington St.

Phoenix, Arizona 85007

Arizona Corporation Commission

**DOCKETED**

APR 28 2005



Re: Johnson Utilities Company- Compliance with Decision Nos. 64062, 65840  
ACC Docket Nos.: W-02234A-00-0371; WS-02987A-99-0583;  
WS-02987A-00-0618; W-02859A-00-0774; W-01395A-00-0784

Dear Mr. Bozzo:

Pursuant to Commission Decision No. 64062 (October 4, 2001), as amended by Decision No. 65840 (April 22, 2003), Johnson Utilities Company ("Johnson Utilities") hereby submits this compliance filing in accordance with the Commission's orders in the above-referenced matter. Enclosed please find Arizona Department of Environmental Quality ("ADEQ") Drinking Water Compliance Status Reports for Johnson Utilities' three **water** systems.

- |    |                   |                   |
|----|-------------------|-------------------|
| 1. | PWS ID # - 11-116 | Sun Valley        |
| 2. | PWS ID # - 11-128 | Johnson Utilities |
| 3. | PWS ID # - 11-245 | Wildhorse         |

...  
...  
...

AZ CORP COMMISSION  
DOCUMENT CONTROL

2005 APR 28 P 4:35

RECEIVED

# FENNEMORE CRAIG

Mr. Brian Bozzo, Compliance Manager

April 28, 2005

Page 2

Johnson Utilities will be filing documentation of compliance with ADEQ regulations for its **wastewater** system under separate cover. Based on the enclosed ADEQ reports, Johnson Utilities is currently in compliance with all ADEQ regulations for its water systems. Should you have any questions, please do not hesitate to contact me. Thank you for your time and consideration in this matter.

Very truly yours,



Patrick J. Black

Enclosures

cc: Brian Tompsett, Johnson Utilities Company (w/enc.)  
Ernest Johnson, Director – Utilities Division (w/enc.)  
Docket Control (w/enc.)

**SUN VALLEY**

**Arizona Department of Environmental Quality**  
**Water Quality Compliance Assurance Unit**  
1110 W. Washington Street, 5415B-1  
Phoenix, AZ 85007

**Drinking Water Compliance Status Report**

**Public Water System Name:** Johnson Utilities – Sun Valley

**Public Water System ID #:** 11-116

**Public Water System Type:** ☒ CO ☐ Non-transient Non-community ☐ Transient Non-community

**Overall Compliance Status:** ☒ No Major Deficiencies ☐ Major Deficiencies

**Monitoring and Reporting Status:** ☒ No Major Deficiencies ☐ Major Deficiencies

Comments:

**Operation and Maintenance Status:** ☒ No Major Deficiencies ☐ Major Deficiencies

Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- |   |   |
|---|---|
| <input type="checkbox"/> unable to maintain 20psi           | <input type="checkbox"/> inadequate storage           |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies             | <input type="checkbox"/> approval of construction     |
| <input type="checkbox"/> certified operator                 | <input type="checkbox"/> other                        |

Date of last inspection / sanitary survey: 12-30-03

**Administrative Orders:**

Is an ADEQ administrative order in effect? ☐ Yes ☒ No

Comments:

**System information:**

Number of Points of Entry 1      Number of Sources 1      Population Served 77

Service Connections 37      Initial Monitoring Year 1996      Initial MAP Year 2002

**Evaluation completed by:** Jim Puckett

**Phone:** 602-771-4649      **Date:** 4-28-05

Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.

**JOHNSON UTILITIES**

**Arizona Department of Environmental Quality**  
**Water Quality Compliance Assurance Unit**  
1110 W. Washington Street, 5415B-1  
Phoenix, AZ 85007

**Drinking Water Compliance Status Report**

**Public Water System Name:** Johnson Utilities

**Public Water System ID #:** 11-128

**Public Water System Type:** ☒ CO ☐ Non-transient Non-community ☐ Transient Non-community

**Overall Compliance Status:** ☒ No Major Deficiencies ☐ Major Deficiencies

**Monitoring and Reporting Status:** ☒ No Major Deficiencies ☐ Major Deficiencies  
**Comments:**

**Operation and Maintenance Status:** ☒ No Major Deficiencies ☐ Major Deficiencies  
**Comments:**

**Major unresolved/ongoing operation and maintenance deficiencies:**

- |   |   |
|---|---|
| <input type="checkbox"/> unable to maintain 20psi           | <input type="checkbox"/> inadequate storage           |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies             | <input type="checkbox"/> approval of construction     |
| <input type="checkbox"/> certified operator                 | <input type="checkbox"/> other                        |

**Date of last inspection / sanitary survey:** 1-15-05

**Administrative Orders:**

**Is an ADEQ administrative order in effect?** ☐ Yes ☒ No

**Comments:**

**System information:**

**Number of Points of Entry** 3 **Number of Sources** 6 **Population Served** 24572

**Service Connections** 8776 **Initial Monitoring Year** 2000 **Initial MAP Year** 2000

**Evaluation completed by:** Jim Puckett

**Phone:** 602-771-4649

**Date:** 2-9-05

Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.

**WILDHORSE**

**Arizona Department of Environmental Quality**  
**Water Quality Compliance Assurance Unit**  
1110 W. Washington Street, 5415B-1  
Phoenix, AZ 85007

**Drinking Water Compliance Status Report**

**Public Water System Name:** Wildhorse

**Public Water System ID #:** 11-245

**Public Water System Type:** ☒ CO ☐ Non-transient Non-community ☐ Transient Non-community

**Overall Compliance Status:** ☒ No Major Deficiencies ☐ Major Deficiencies

**Monitoring and Reporting Status:** ☒ No Major Deficiencies ☐ Major Deficiencies

Comments:

**Operation and Maintenance Status:** ☒ No Major Deficiencies ☐ Major Deficiencies

Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- |   |   |
|---|---|
| <input type="checkbox"/> unable to maintain 20psi           | <input type="checkbox"/> inadequate storage           |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies             | <input type="checkbox"/> approval of construction     |
| <input type="checkbox"/> certified operator                 | <input type="checkbox"/> other                        |

Date of last inspection / sanitary survey: none

**Administrative Orders:**

Is an ADEQ administrative order in effect? ☐ Yes ☒ No

Comments:

**System information:**

Number of Points of Entry 1 Number of Sources 1 Population Served 60

Service Connections 21 Initial Monitoring Year 2006 Initial MAP Year 2006

**Evaluation completed by:** Jim Puckett

**Phone:** 602-771-4649 **Date:** 4-27-05

Based upon data submitted by the water system, ADEQ has determine that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.